



14th Floor, Centre Tower
3300 Bloor Street West
Toronto, Ontario
Canada M8X 2X4
Tel.: 416.734.3300
Fax: 416.231.1626
Toll Free: 1.877.682.8772

www.tssa.org

July 12, 2012

DAVID SMITH
BRANHAM CORPORATION
207 EILER AVE
LOUISVILLE KY 40214
US

Service Request Type: BPV-Fitting Registration
Service Request No.: 836990
Your Reference No.:

Dear DAVID SMITH,

Technical Standards and Safety Authority (TSSA) is pleased to inform you that your submission on June 26, 2012 has been reviewed and registered as follows:

CRN No.: 0D15392.5

Reference No.:

Main Design No.: FLEXIBLE HOSE ASSEMBLIES: CRN-1 TO CRN-40 - SEE SCOPE OF REGISTRATION (DATED 6/4/2012)

Expiry Date: 12-Jul-2022

Please be advised that a valid quality control system must be maintained for the fitting registration to remain valid until the expiry date.

A stamped copy of the approved registration and invoice for engineering services will be mailed to you shortly. Should you have any questions or require further assistance, however, please contact a Customer Service Advisor at 1.877.682.TSSA (8772) or e-mail customerservices@tssa.org. We will be happy to assist you. When contacting TSSA regarding this file, please refer to the Service Request number provided above.

Yours truly,

Wendy Du, P.Eng.
Technical Standards & Safety Authority
Boilers & Pressure Vessels Safety Program
Tel.: 416-734-3566
Fax: 416-231-6183
Email: wdu@tssa.org